



V5 SOFTWARE AND FIRMWARE REVISIONS

SOFTWARE

Version 5.0 Build 30 – Initial Release 6-6-18

- Proper Firmware Version – 5.0 Build 30

Version 5.0 Build 31 – Release 6-26-18

- Added popup screen to tell user to make sure ignition power was cycled before TPS autoset
- Updated minimum zoom resolution in Active Speed Management when units are MPH
- Renamed transmission ICF dropdown from "GM 4L60/5E (2009+)" to "GM 4L70E (2009+)"
- Corrected transmission ICF pin mapping locked pins for Ford transmissions
- Custom Injector setup clarified to not include 4 and 6 cylinder engines at this time

- Proper Firmware Version – 5.0 Build 30

Version 5.0 Build 32 – Release 9-24-18

- Fixed bug in the log viewer that caused channel name to disappear at the top of the screen.
- Fixed bug in logger that caused long logs to be broken into smaller logs improperly. This was causing the subsequent logs to have the inputs/outputs not viewable.
- When updating the Target Air Fuel Table while online the fuel table is now updated and sent to the ECU as well.
- Fixed bug with software not always importing driveshaft curves into Traction Control
- Fixed bug that caused data log viewer parameters to disappear when hitting enter or escape.

- Proper Firmware Version – 5.0 Build 30

FIRMWARE

Version HEFI_5000300.eep (5.0 Build 30) – Initial Release 6-6-18

- Compatible Software Versions - 5.0 Build 30, 5.0 Build 31, and 5.0 Build 32