



**P/N 558-304
HEI ADAPTER HARNESS**

The use of this adapter requires that the software and firmware versions be at the following levels or higher:

Software – Version 1.1.5 and higher.

Firmware – Version 279 or numerically higher.

If you have earlier software and firmware versions, you can download both at Holley's website. Use the following web address:

<http://www.holley.com/TechService/Library.asp>

Instructions on updating the firmware are found in the software's Help/Instructions section under "Updating Firmware".

199R10557

Date: 5-27-10