



**FAN SPACERS
P/N 2391, 2392, & 2393**

Do not overtighten max. 20 ft./lbs.

Fan should not be closer than 1-1/4" to radiator.

If replacing the fan clutch, use a 2" spacer. Spacers can be combined to get other thicknesses up to the recommended maximum 3 inches. Use 5/16" capscrews (3/4" longer than total thickness).

**199R11356
Date: 6-19-17**



**FAN SPACERS
P/N 2391, 2392, & 2393**

Do not overtighten max. 20 ft./lbs.

Fan should not be closer than 1-1/4" to radiator.

If replacing the fan clutch, use a 2" spacer. Spacers can be combined to get other thicknesses up to the recommended maximum 3 inches. Use 5/16" capscrews (3/4" longer than total thickness).

**199R11356
Date: 6-19-17**



**FAN SPACERS
P/N 2391, 2392, & 2393**

Do not overtighten max. 20 ft./lbs.

Fan should not be closer than 1-1/4" to radiator.

If replacing the fan clutch, use a 2" spacer. Spacers can be combined to get other thicknesses up to the recommended maximum 3 inches. Use 5/16" capscrews (3/4" longer than total thickness).

**199R11356
Date: 6-19-17**



**FAN SPACERS
P/N 2391, 2392, & 2393**

Do not overtighten max. 20 ft./lbs.

Fan should not be closer than 1-1/4" to radiator.

If replacing the fan clutch, use a 2" spacer. Spacers can be combined to get other thicknesses up to the recommended maximum 3 inches. Use 5/16" capscrews (3/4" longer than total thickness).

**199R11356
Date: 6-19-17**



**FAN SPACERS
P/N 2391, 2392, & 2393**

Do not overtighten max. 20 ft./lbs.

Fan should not be closer than 1-1/4" to radiator.

If replacing the fan clutch, use a 2" spacer. Spacers can be combined to get other thicknesses up to the recommended maximum 3 inches. Use 5/16" capscrews (3/4" longer than total thickness).

**199R11356
Date: 6-19-17**



**FAN SPACERS
P/N 2391, 2392, & 2393**

Do not overtighten max. 20 ft./lbs.

Fan should not be closer than 1-1/4" to radiator.

If replacing the fan clutch, use a 2" spacer. Spacers can be combined to get other thicknesses up to the recommended maximum 3 inches. Use 5/16" capscrews (3/4" longer than total thickness).

**199R11356
Date: 6-19-17**