

# **ADDENDUM**

---

---

## **PN 7763/PN 77631 Solenoids**

The solenoids provided with this kit are calibrated for proper wastegate response time. For this reason MSD does not recommend the use of other solenoids with this boost controller. Do not attempt to adjust the calibration of the solenoids. Doing so can render the solenoid un-responsive, or can lead to excessive CO2 consumption. In the event the solenoids need to be recalibrated due to unresponsiveness or CO2 consumption, please contact the RMA department at 915-855-7123 8:00am-5:00pm Mountain Time for service.

---

**MSD** • [WWW.MSDPERFORMANCE.COM](http://WWW.MSDPERFORMANCE.COM) • (915) 855-7123 • FAX (915) 857-3344  
FRM31794 © 2013 Autotronic Controls Corporation Revised 11/13 Printed in U.S.A.

# **ADDENDUM**

---

---

## **PN 7763/PN 77631 Solenoids**

The solenoids provided with this kit are calibrated for proper wastegate response time. For this reason MSD does not recommend the use of other solenoids with this boost controller. Do not attempt to adjust the calibration of the solenoids. Doing so can render the solenoid un-responsive, or can lead to excessive CO2 consumption. In the event the solenoids need to be recalibrated due to unresponsiveness or CO2 consumption, please contact the RMA department at 915-855-7123 8:00am-5:00pm Mountain Time for service.

---

**MSD** • [WWW.MSDPERFORMANCE.COM](http://WWW.MSDPERFORMANCE.COM) • (915) 855-7123 • FAX (915) 857-3344  
FRM31794 © 2013 Autotronic Controls Corporation Revised 11/13 Printed in U.S.A.