



*** See Note**

Note: Some 7AL-3 Users may experience a harsh rev-limit with the PowerGrid attached and controlling the rev-limiting functions of the 7AL-3. In this case, MSD recommends using the chips in the 7AL-3.